Visual Health Check

Custo	omer Inf	ormatic	on									
Name	•							Customer Ref	ference			
WIP Number Date 11/12/2020 Registration Number OY66XOF				Next MOT								
				Next Service or in miles								
				OY66XOF				Current Milea	ge	81121		
VIN	ele Deta	ile		XE				Annual Mileag	ge			
venic			_								Fixed Price	Audhariand
Inch	ection	Amber	Green	Section				Recomme	endation		Fitted Price	Authorised
msp	ection	1000000000	-		Engine ur	dertrav is	damaged.	Recommend the	undertrav is rep	laced to prevent dirt and	454.00	
		V		Bodywork				the underside of			154.30	
	Bodywork - 2				The O/S undertray that runs the length of the vehicle is damaged. Recommend the undertray is replaced to prevent dirt and debris from collecting around the underside of the vehicle.						137.04	
				Bodywork - 3	Fuel filler	cap is broi	ken. will re	quire replaceme	nt		25.42	
			V	Wheels							0.00	
	✓ Washers/Wipers/Horn				The passenger side wiper is split in the centre. recommend the wiper is replaced. (Recommend wipers are replaced in pairs for even wear)						0.00	
	V			Lights		amount o		ation within the h	nigh level stop la	mp.	388.22	
			V	Transmission							0.00	
	V			Electrical						ne non start issue.	816.08	
				Interior	will require programming to the vehicle via SDD once fitted.						0.00	
			V								0.00	
			V	Air Con								
			V	Engine Oil							0.00	
	Engine				The fuel cooler on the underside of the vehicle has been hit/damaged. Recommend the cooler is replaced as it could be weakened and leak over time.						299.22	
			V	Brake Fluid							0.00	
			V	Cooling System							0.00	
		V		Exhaust						ad to D.E.F dosing prevent any further faults	1,230.54	
			V	Steering/Suspension Front							0.00	
			V	Steering/Suspension Rear							0.00	
	V			Front Brakes				orroded due to v re replaced	vehicle being stat	tionary for a long time.	595.17	
Rear Brakes			Rear Brakes	Rear brake discs are heavily corroded due to vehicle being stationary for a long time. Recommend the front brakes are replaced						528.64		
				4 Wheel Alignment							0.00	
				Battery							0.00	
				Puncture							0.00	
V				Air Con Service							0.00	
				Misc							0.00	
		Front I	Pads: 9n		iscs: heavil	y cor	Rear Pa	ds/Shoes: 7mm	Rear Dis	cs: heavily cor Measu	urement:MM R	
	Tyre	Report		Tyre	Outer	Middle	Inner	Damaged	Size	Make Fitted Make Quoted	Fitted Price	Authorised
			V	Front Left	5	5	5		225/45 R18	Buget tyres fitted	0.00	
				Notes								
			V	Front Right	5	5	5		225/45 R18	Buget tyres fitted	0.00	
				Notes								
			V	Rear Right	5	4	5		225/45 R18	Buget tyres fitted	0.00	
			SECTION SECTION	Notes		لٺ	لت					_
		BESSEL	V	Rear Left	5	4	5		225/45 R18	Buget tyres fitted	0.00	
				Real Left	5	4	3		223/43 K16	Duget tyres fitted	0.00	

	Notes							
	Spare					0.00		
	Notes							
	Tyre labour					0.00		
					Total scheduled	£0.00		
					Total identified	£4,174.63		
					Total authorised Incl. Tax	£0.00		
	Total invoice value (including original scheduled work)							
	Please note that t	hese pric	es may	be subject to change.				
Technician	Callum Harrington			Service Advisor	Shelby Cole			
Customer Signature								
Printed on 14 December	2020 14:04							